



USED IF:

- if plate has capped-off threaded standoff on front of engine, plate is normally ribbed also drive is female slotted drive

- then the engine requires:

- (1) 32608 BC-3110 Drive Joint .500  
Normally sent Reverse Rotation  
Direct Rotation Shown
- (1) 37626 821874 Drive Pin \*Special w/shoulder\*

PERKINS ADAPTER

SCALE: FULL | DATE: 4/12/88 | PART # 060602

**gmp** GLENDINNING MARINE  
RT. 5 BOX 188 CONWAY SC 29526